


From: Ivor Kruger [mailto:ivor@niche-technologies.co.za]
Sent: 25 September 2007 03:45 PM
To: 'LGEAP CIC'
Subject: RE: LG Customer Enquiry-[Ivor Kruger]

6871EC1025 (B, c, or D etc) are the replacement part numbers.
What was the number of the original pcb's that were recalled?
It was for the LD-12AS1 and LD-12AW2, LD-4050W etc models.

Thanks
Ivor.

From: LGEAP CIC [mailto:CIC_AP@lge.com]
Sent: 24 September 2007 12:28 PM
To: Ivor Kruger
Subject: LG Customer Enquiry-[Ivor Kruger]

-----Reply to Customer Enquiry-----



IMPORTANT NOTICE This email, including any attachments is a confidential communication between the sender and the intended recipient. They may contain legally privileged information or copyright. You should not read, copy, use or disclose the content without authorisation. If you are not the intended recipient or you have received this email in error please contact us at once by return email and then delete both messages. We do not accept liability in connection with computer virus, data corruption, delay, interruption, unauthorised access or unauthorised amendment. This notice should not be removed.

-----Customer Details-----

Name : Ivor Kruger
Street :
City :
State :
Post Code :
Tel :
Country/Region : Australia
E-mail : ivor@niche-technologies.co.za

-----Original Customer Enquiry-----

Received Date : 24/9/2007 19:33:28
The type of inquiry : Parts or Accessories

Product/Model No. : Dishwasher/LD-12AS1

What was the part number of those main boards that were all recalled a couple of years back? And what was the part number of the replacements? It was for the LD-12AS1 dishwashers -and others. I suspect I still have one in my machine. One corner near a relay has melted itself right through the board. Lucky the whole thing didn't catch alight with all that sound deading carpeting material inside the door!! Much Thanks Ivor.
